

# STRUCTURAL STABILITY CERTIFICATE

This is to certify that we have visited, inspected, tested & analyzed the MAHARAJA AGARSAIN SCHOOL, situated at Bhorgarh, Bawana Narela Road, Narela Delhi.

The structure is in good condition. We have analyzed the structure as per the latest codes for seismic safety (is-1893) for zone-4 and relevant codes as per NBC (**National Building Code**) of India updated to the latest version. **It is our view that this structure is safe for occupation.** 

por JYOTI

(Structure Engineer) MCD Approved. License No.-SE-0327

JYOTI YADUVANSHI & ASSOCIATES MCD LICENSE NO.: SE/0327 B.TECH (CIVIL) T-50/2 M.E.S Qutrs, O.D Shakur Basti



Yaduvanshi & Associates

Mobile:- 9910744590, E-Mail:- archjdhrra@gmail.com

#### CERTIFICATES OF STRUCTURAL SAFETY

Following certificate is submitted after site visit and proper investigation for The MAHARAJA AGARSAIN PUBLIC SCHOOL, situated at Bhorgarh, Bawana Narela Road ,Narela Delhi. The school was constructed and maintained in span of 30 years at different intervals.

Details of building blocks are:-

Certified that this structural stability certificate has been issued after taking into consideration.

- a) The National Building Code of India including the structural design of foundation, masonary, Timber, plain concrete, reinforced concrete, restressed concrete and structural Steel shall be carried out in accordance with part-vi structural design section-1 loads section-2 Foundation section 3 wood Section-4 masonary section-5 concrete and section-6 Steel of National Building Code.
- b) All relevant standards prescribed by Bureau of Indian Standards including the standard given in IFSC code 13920-1993, 4326-1993, 13828-1993, 13827-1993, 13935-1993, 456: 2000, 800-1984, 801-1975, 875 (part-2):1987, 875 (part-3):1987, 875 (part-4):1987, 883: 1966, 1904:1987, 1905: 1987, 2911(Part-1):section-1:1979, 1893: 2002 for general structural safety cyclone/ wind protection, Earthquake protection.
- i) Certified that the above mentioned building (include in solar panels) as exist as on date fulfill all the structural safety and safety requirements.

SIGNED BY:	COUNT
SIGNED BY: JYOTI SOCIATES Signature of Structure Engineer: JYOTI SINGH Name of Structure Engineer: JYOTI SINGH Address: T50/2, MES Otts: Ordinance depot,	Signatur
Name of Structure Engineer: JYOTI SINGH	Name of
Address: T50/2, MES Office Ordinance depot,	
	Address

COUNTER SIGNED BY:

re of owner(s) of Owner(s): Maharaja Agarsain Education

Soceity Bawana Rocel Marcla Sething Date:

Shakur Basti, New Delhi.

Date:

In addition to the certifications given in SI. No. (i) and (ii) above, it is also certified that:

- ii) The above mentioned building (as exits as on date), in whole or in any part, does not have any misuse of any kind as permitted, or subsequent permitted change in use by the competent authority as per law.
- iii) Any tangible item on the rooftop of the above mentioned building (as exists as on date), such as water tank, solar panel are in accordance with the necessary permission / clearances such as , fire clearance, pollution clearance, etc.

SIGNED BY: Souse	
Signature of owner(s)	
Name of owner(s) <u>Maharaja Agarsain Education Soceity</u> Address of owner(s): /3awoma Road Marula	nolli -40
Address of owner(s): / Jawoma Nagu Nava	

Please note that, the above certification is based on details investigation mentioned in report.



Mobile:- 9910744590, E-Mail:- archjdhrra@gmail.com

## To whom so ever it may concern

We are appointed as a structure consultant by the MAHARAJA AGARSAIN PUBLIC SCHOOL, situated at Bhorgarh, Bawana Narela Road, Narela Delhi. to conduct the structural audit report of the building in reference to MCD letter number no. ...........(Bldg.) NEZ/2020.

Our team visited the premises from 03<sup>rd</sup> October 2021 to 16<sup>th</sup> October 2021 to analyse the safety of the structure and to check the structure for existing load for example dead load and live load as per IS codes.

Being conducted non destructive test for example rebound hammer test and prepare detailed report attached as per CPWD manual repair and rehabilitation.

Detail observation analysis is documented in report which has following sections.

- Annexure-A
- Attachment-1
- Annexure B
- Attachment-2

Rebound hammer analysis Rebound hammer readings Soil moisture analysis Soil moisture readings

On the basis of testing and inspection it has been found that the structure is safe and sound and meets the criteria for earthquake resistance building.

Thanking you,

### For Yaduvanshi & Associates



Mob: 9910744590



#### Enclosures:

- i) Copy of structure certificate.
- ii) Inspection Report